

S1 Overall Front



S1 PR side



S1 PL side



S1 dutchman corner plinth



S1 ivy plants on plinth



S1 back deterioriated stone; surface loss



S1 condition detail



S1 base of upper





S1 detail biological growth

S1 detail horizontal surface





S1 foot weathered limestone

S1 foot detail





S1 presumed lichen detail

S1 detail





S1 detail


S1 plastic repair mortar join



S1 crack, delamination on plinth



S2 PL side



S2 Overall Front



S2 PR side sculpture



S2 PR side plinth



S2 plinth base detail



S2 plinth back



S2 growth, deterioriation



S2 detail PL side



S2 dutchman



S2 detail




S2 back detail



S2 plastic fill prior repair



S2 detail



S2 carving detail



S2 detail





S2 surface detail

S2 missing foot prior repair





S2 detail

S2 stone surface loss





S2 detail leg S2 detail plinth





S2 detail dutchman fill

S2 carving better preserved





S2 detail carving

S2 carving detail





S2 surface cond detail

S. Allée from stair landing



Panoramic - South Allée